

# The Imaging Source Helpdesk

Knowledgebase > Troubleshooting > NVidia TX2: Fehlende Kameraeigenschaften

---

## NVidia TX2: Fehlende Kameraeigenschaften

S.Geißler - 2021-07-19 - Troubleshooting

If Gain Auto is missing on USB cameras, then the Jetpack must be updated to version 4.2.1.

Version 4.2.2 fixes the issue of half frame rates.